

(产品中有害物质的名称及含量)
China EEP Hazardous Substances Information

Exactive Series

(Exactive Plus, Exactive Plus EMR, Q Exactive, Q Exactive Focus, Q Exactive HF, Q Exactive Plus)

部件名称 Component Name	有害物质 Hazardous Substances					
	铅 (Pb)	汞 (Hg)	镉 (Cd)	六价铬 (Cr(VI))	多溴联苯 (PBB)	多溴二苯醚 (PBDE)
住房 Housing	O	O	O	O	O	O
电路板 PCBAs	X	O	O	O	O	O
电子组件 Electronic Assemblies	O	O	O	O	O	O
金工 Metal Parts	X	O	O	O	O	O
塑料 Plastics	O	O	O	O	O	O
玻璃和陶瓷 Glass and Ceramics	O	O	O	O	O	O

(本表格依据SJ/T11364的规定编制) This table is compiled according to SJ/T 11364 standard.



O: (表示该有害物质在该部件所有均质材料中的含量均在GB/T26572规定的限量要求以下.)
Indicates that the concentration of the hazardous substance in all homogeneous materials for the part is below the relevant threshold of the GB/T 26572 standard.

X: (表示该有害物质至少在该部件的某一均质材料中的含量超出GB/T26572规定的限量要.)
Indicates that the concentration of the hazardous substance in at least one homogenous material of the part is above the relevant threshold of the GB/T 26572 standard.